

Assessing landslide dam hazards in Aotearoa New Zealand: a data driven approach.

Regine Morgenstern¹, Andrea Wolter¹, Chris Massey¹, Brenda Rosser¹, Simon C. Cox² and Biljana Lukovic¹

¹GNS Science, Lower Hutt, New Zealand

²GNS Science, Dunedin, New Zealand

Email: r.morgenstern@gns.cri.nz

Abstract: Landslide dams form when debris from a landslide blocks the watercourse of a valley and if they fail rapidly, they can pose a significant and catastrophic hazard to downstream life, property and infrastructure. Landslide dams and their remnants occur widely throughout Aotearoa New Zealand, being a function of the maritime climate and active tectonic setting, as well as the high relief and/or steep topography. At least 500 natural dams have formed here in the last few decades, with the 2016 Kaikōura earthquake contributing to the majority (94%). Many of these have been in remote, mountainous terrain; however, their frequency and potential for causing loss or harm should they occur in populated areas and fail rapidly, can have huge consequences. Here we present ongoing work to better understand dam formation potential, stability, breach mechanisms and downstream impacts, by utilizing a combination of techniques and data including a new geospatial database, field-based monitoring, hindcast and forecast modelling and expert judgement based on observations relating to the previous performance of landslide dams.

The recent completion of version 1.0 of the New Zealand Landslide Dam Database presents the compilation of historical and recent efforts to map landslide dams in New Zealand. It includes 1036 dams, each of which have source area, debris trail, dam and lake polygons mapped, where possible, as well as a categorical measure of the data quality. The location of each dam is represented by a point at the upstream end of the dam, and attribute information includes: dimensions and volumes; triggering mechanisms and dates; geological parameters; catchment and valley properties; and breach details. Our data show that most of the recent landslide dams in New Zealand have failed within the first year of their formation, often triggered by the first high intensity or prolonged rainfall – post dam formation – which caused overtopping. The database is being used to further investigate and analyse the formation potential, longevity, and stability of natural dams across the country.

Detailed case studies are also needed to help calibrate these historical regional-scale observations and to provide better spatiotemporal resolution for assessing longevity, failure modes and downstream impacts. Here, we summarize a method for assessing these post-formation, drawing on two detailed monitoring campaigns: the Kaiwhata (rainfall-induced) and Hapuku (earthquake-induced) landslide dams. This includes the following steps: (1) perform initial, desktop breach inundation modelling to determine scale of hazard and impact utilizing empirical dam-breach relationships; (2) collect high-resolution topographic surveys of the dam and downstream floodplain, using both field-based and remote sensing techniques; (3) investigate and identify dam-forming materials; (4) revise breach mechanisms/models using field data to identify dam failure scenarios; (5) revise numerical simulations to more clearly define the likely area of inundation, for each scenario; and (6) overlay dam failure and inundation scenario models on asset maps to identify life, property and infrastructure that are potentially at risk. By following such a method, the impacts posed by landslide dam-breach hazards can be better managed.

Keywords: Landslide dam, dam outburst flood hazard, monitoring, rapid response, database, GIS



The XIV Congress of the International Association for Engineering Geology and the Environment

Engineering Geology for a Habitable Earth

Assessing landslide dam hazards in Aotearoa New Zealand: a data driven approach

Regine Morgenstern, Andrea Wolter, Chris Massey,
Brenda Rosser, Simon C. Cox and Biljana Lukovic

GNS Science, New Zealand



Presentation overview and introduction

Landslide dams in New Zealand (NZ)

- >500 formed in last few decades
- NZ Landslide Dam Database

Methods for assessing landslide dams

- **Case studies:** assessing failure modes, longevity and downstream impacts
 - **Kaiwhata** landslide dam
 - **Hapuku** landslide dam

Brumadinho dam disaster (Brazil) - 25 Jan 2019 270 deaths



A rapid failure and breach event can have devastating impacts on downstream life and critical infrastructure.


Background – landslide dams in NZ

NZ Landslide Dam Database (NZLDD)


assessing landslide dam formation potential, stability and longevity.

- Significant increase in catalogued landslide dams globally (1434, Shan et al. 2020)
- Contains **1036** dams, with a representative subset of **265**
- Includes dams generated during the 2016 Kaikōura earthquake

Early 2000s (Korup 2004)



2023 (Morgenstern et al. in press)



Data (OSF)




Metadata



NZLDD - design

- ArcGIS geodatabase
 - 5 feature classes + 1 table
- Site ID that links all components



S: Source
DT: Debris Trail
D: Dam
L: Lake

Bold = all dams (where possible)
Italics = subset only
All other = ArcPy (where possible)

DamSite (Master Point Feature Class)

OBJECTID	
DamSiteID (PK)	●
SiteID	
X_Dam	
Y_Dam	
Z_Dam	
H_Dam	
W_Dam	
L_Dam	
V_Dam	
H_LS	
R_LS	
R_LS_3D	
L_LS	
H_R_ratio	
H_R3D_ratio	
H_L_ratio	
A_LS_debris_sum	
V_LS_debris_sum	
Material_LS	
Type_LS	
Trigger	
Type_Dam	
DBI	
Upstream_Catchment_Area	
W_Channel_at_Dam	
Grad_Channel_at_Dam	
DateFormed_Dam	
FailureMech_Dam	
Dam_breach	
Dam_breach_details	
Dam_Stability	
Q_at_Failure	
Confidence	
Comments	
References	
SUBSET	
MetadataID (FK)	

Dam site-specific info

QualityRanking (Table)

OBJECTID	
MetadataID (PK)	
Reference	
Reference_full	
Data_Source	
Mapping_Method	
QR_Method	
Completeness	
QR_Completeness	
Location_Accuracy	
Polygon_Accuracy	
Mapping_Scale	
QR_Accuracy	
QR_OVERALL	

Dataset-specific info

Source (Polygon Feature Class)

OBJECTID	
SourceID (PK)	◻
SiteID	
Source_Geology	
V_S	
References	
SUBSET	
Shape_Length	
Shape_Area	

Source-specific info

DebrisTrail (Polygon Feature Class)

OBJECTID	
DebrisTrailID (PK)	◻
SiteID	
References	
SUBSET	
Shape_Length	
Shape_Area	

Debris trail-specific info

Dam (Polygon Feature Class)

OBJECTID	
DamID (PK)	◻
SiteID	
Dens_Dam	
References	
SUBSET	
Shape_Length	
Shape_Area	

Dam-specific info

Lake (Polygon Feature Class)

OBJECTID	
LakeID (PK)	◻
SiteID	
D_Lake	
V_Lake	
References	
SUBSET	
Shape_Length	
Shape_Area	

Lake-specific info

PK: primary key; FK: foreign key

NZLDD

Morgenstern et al. (in press)











Methods

- Mapping of newly identified dams
- Compilation and re-mapping of previous data

Statistics

Majority of dams in the database have formed:

- In greywacke basement terrane (60-68%)
- Rock avalanches, falls, slides and topples (51-52%) - Hungr et al. (2014) classification
- From EQ-trigger (30-62%), where classified
- Dam Type I & II (83-87%) - Costa & Schuster (1988)
- Have since breached completely and no longer impound water (59-63%)



Significant dam-forming events

Event	Type	# dams
2020 Gisborne	rainfall	5
2016 Kaikōura	earthquake	470
2011 Hawkes Bay	rainfall	3
2009 Fiordland	earthquake	3
2004 Manawatu	rainfall	5
2003 Fiordland	earthquake	10
1968 Inangahua	earthquake	40
1929 Murchison	earthquake	61


Left: exclude Kaikōura; Right: full database




Assessing landslide dams in NZ - methods

6-step approach:

1. Initial desktop modelling to determine scale of hazard and impact
2. Collect high-resolution topographic surveys of the dam and downstream floodplain (RTK, TLS, UAV, LiDAR, lake level, rain gauge, mapping)
3. Investigate and identify dam-forming materials (PSD)
4. Revise breach mechanisms/models using field data to identify dam failure scenarios
5. Revise numerical simulations for each scenario
6. Overlay dam failure and inundation scenario models on asset maps to identify life, property and infrastructure that are potentially at risk



Case study 1: Kaiwhata landslide dam



Landslide dammed Kaiwhata River
1st June 2020 following heavy rain


Data collected over 4 weeks – from just after formation to immediately post-failure



Dimensionless Blockage Index (DBI) tool

Probability of dam failure: regional-scale assessment based on dam geometry and catchment area (stream power)

Kaiwhata – event timeline




June 6th

Field data indicated:


- dam height: ~**16 m**
- dam volume: ~**110,000 m³**
- lake volume: **600,000 m³**
- PSD: **D50** was **3 mm** (mudstone with clay + glauconitic sandstone)

Dam cross-section



By June 12th

- **Outflow channel** had formed
- Seepage and slumping observed
- Lake level was still **1.2 m below max**



June 12th



June 13th

- Dam failed 9.15pm (steady all-day rain)
- Released ~**1 M m³** water in **<1.5 hours**
- Peak discharge: **900 m³/s** (100 yr flood: **15 m³/s**)
- Full breach: due to throughflow and slumping; ultimately via overtopping


June 14th



Kaiwhata – flood extent

Trash line surveying – field mapping of floodplain day after the event

- Entire floodplain inundated with **1-2 m** of water (max **600 m wide** and **6 m depth**)
- Failure occurred in **multiple pulses**
- No one hurt, no buildings or infrastructure damaged




Kaiwhata – scenario modelling

The breach and inundation models were trained using empirical data

- lake level and volume
- rainfall
- eyewitness accounts
- breach hydrograph
- flood extent



- **Back analysis of dam failure** – comparing modelled flood depths and extents with field-mapped depths and extents
- Initial model: overestimated water depths and velocities – importance of **field data** to check input parameters and **verify model results**




Case study 2: Hapuku landslide dam

M_w 7.8 Kaikōura Earthquake
(14 Nov 2016)


- Regional-scale response
- ~30 faults ruptures
- c. 30,000 landslides
- Initial assessment: ~200 landslide dams
- Now mapped: **470 landslide dams** (NZLDD)
- **Life safety risk and impact on infrastructure:** stability of these dams (7 in particular) was a major concern
- Hapuku:
 - 9 km upstream of main highway + rail corridor



Hapuku – event timeline



From 27 data epochs...



14th Nov 2016 (T-0)

- 80 m high dam forms with ~1 M m³ lake
- Seepage, piping + headward erosion begins
- PSD: **D50** was **4-30 mm** (greywacke)

28th Mar–20th Apr 2017 (T ~4.5 months)



- 1st mod-intensity rainfall event (cyclones)
- Partial breach 1: overtopping + gradual erosion of ~**0.4 M m³**, peak discharge of up to **12 m³/s**
- Debris flood **9 km** downstream **40 mins** later

12-19th Sep 2017 (T 10 months)


- Partial breach 2
- Not associated with a storm
- Peak discharge of **90 m³/s**

17th Nov–3rd Dec 2018 (T 2 years)


- Partial breach 3: **1.4 M m³** erosion
- Most significant erosion event
- Spring storm following 4 months of dry weather




Wolter et al. (2022)



Hapuku – event timeline



Partial breach 1



28th Mar–20th Apr 2017 (T ~4.5 months)



- 1st mod-intensity rainfall event (cyclones)
- Partial breach 1: overtopping + gradual erosion of ~**0.4 M m³**, peak discharge of up to **12 m³/s**
- Debris flood **9 km** downstream **40 mins** later

12-19th Sep 2017 (T 10 months)


- Partial breach 2
- Not associated with a storm
- Peak discharge of **90 m³/s**

17th Nov–3rd Dec 2018 (T 2 years)

- Partial breach 3: **1.4 M m³** erosion
- Most significant erosion event
- Spring storm following 4 months of dry weather




Wolter et al. (2022)



Partial breach 1
RAMMs modelling

Kaiwhata vs Hapuku landslide dams

	Kaiwhata	Hapuku
Emplacement mechanism	Debris avalanche, single event	Rock slide, multiple pulses, highly sheared, debris consolidated post-emplacement
Source material type	Soft mudstone	Hard greywacke
Source material UCS	2 MPa	100 MPa
Source material age	Neogene (23-2.6 Ma)	Early Cretaceous (145-100 Ma)
Deposit D50	3 mm	4-30 mm
Lake volume (lowest point on dam crest)	1 M m ³	1.2 M m ³
Peak breach discharge	900 m ³ /s	12 m ³ /s
Breach type	Complete, rapid within 1.5 hours, overtopping	Partial, gradual headward erosion over ~1 month, followed by multiple overtopping events
Longevity	4 weeks	4.5 months (partial); 7+ years
Lake status	Fully evacuated	Remnant lake



NZ landslide dams – more information



www.slidenz.net



What is a landslide dam?

11/03/2021



Hapuku landslide dam tour 2019

15/04/2021



Landslide dam hazards:
assessing their formation, failure
modes, longevity and
downstream impacts

06/04/2021

Morgenstern et al. (in press) The New Zealand landslide dam database, v1.0. *Landslides*





Conclusions



- New **NZLDD** – added to global datasets to assess landslide dam formation potential, stability and longevity
- **High resolution data** and other field data are required to assess landslide dam hazards and monitor and quantify dam evolution. They **show the complexity** of dam breach and evolution processes, which are often oversimplified
- The **three main factors** that contributed to dam stability and longevity are **source material** and **volume, emplacement mechanism** and **catchment characteristics**
- **Empirical data** are used to train, revise and calibrate breach and inundation scenario models to **more accurately inform life safety risk** and **manage potential impacts** on downstream infrastructure in the event of a rapid dam failure





Thank you!

r.morgenstern@gns.cri.nz

